USA Ground Operations CIL Sheet AUG 2 3 1939

Critical Item: Valve, Solenoid

NASA Part No: None

Criticality Category: 18

Total Quantity: 2

Mfg/Part No:

System:

ASCO / 8344G82

Facility Water System

Find No.	Qty	Area	PMN	Baseline	
A156606 (SV-68)	1	Pad-A	K60-0060	007.00	79K06011 / 13
A526623 (SV-487)	1	Pad-A	K60-0060	007.00	79K06011 / 8

Function:

Controls air supply to flow control valve to pressurize open side of the actuator for the associated water control valve and provides a capability to vent the close side of the actuator for the associated water control

Failure Mode No. Failure Mode	Failure Cause Failure Effect	Detection Method	Crit
09SY03A-001.013	Binding, corrosion, contamination, or failure of internal	Time to Effect	Cat
·	piece part	Water valve position switch	18
Fail closed	J	1	_
	Loss of capability to pressurize open side of actuator on associated water control valve and allow firex/deluge water flow to the associated area. Possible loss of life and/or vehicle during a hazardous condition.	Immediate	

ACCEPTANCE RATIONALE

Design:

- Rated working pressure 125 psid.
- Actual working pressure 125 psid.

Test:

- OMI M2088 requires cycling of perimeter area water valves to verify proper operation.
- OMRSD, File VI requires verification of the operational function of the water valves in all modes of operation annually and at replacement. (Note: Water valve operational function verification ensures valve opens within design opening rate which also verifies solenoid valve has not failed.)

Inspection:

OMI 6045 requires the inspection of the firex valves for signs of corrosion and/or contamination.

Failure History:

- · Current data on test failures, unexplained anomalies, and other failures experienced during ground processing activities can be found in the PRACA database. The PRACA database was researched and no failure data was found on this component in the critical failure mode.
- The GIDEP failure data interchange was researched and no failure data was found on this component in

Operational Use:

Correcting Action	
	Timeframe
There is no action which can be taken to mitigate the failure effect.	1
	timeframe does not apply.